



บริษัท สหเศรษฐ์ ออชั่น จำกัด  
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Maker KUBOTA Model L2600 Serial L2600-18471

\*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

\*This report is only for your reference. We are not responsible for the actual condition of checked item

\*\*\* THAILAND DUTY PAID /ชำระอากรนำเข้าแล้ว

| Category             | Type                 | Maker   | Model |
|----------------------|----------------------|---------|-------|
| AGRICULTURAL TRACTOR | AGRICULTURAL TRACTOR | KUBOTA  | L2600 |
| Serial               | Engine               | Chassis | Year  |
| L2600-18471          | V1500-10140          |         |       |

| Check point                |                                                    |
|----------------------------|----------------------------------------------------|
| Operator                   | Roof                                               |
| Monitor Panel              | Normal — แสดงผลครบ                                 |
| Hour Meter Activity        | Normal — 5858                                      |
| Air Condition              | NONE                                               |
| Engine Operation           |                                                    |
| Number of Pistons          | 4 Pistons                                          |
| Fuel Type                  | Diesel                                             |
| Engine Noise               | Fair                                               |
| Black-White Smoke          | Fair                                               |
| Type Transmition           | Manual                                             |
| Water Leak form Water Pump | Normal                                             |
| Water Leak form Radiater   | Normal                                             |
| Hydraulic System           |                                                    |
| Oil Leak form Velve,Hose   | Normal                                             |
| HYD. Pump Condition        | Repair                                             |
| Hydraulic Oil              | Repair                                             |
| General Working Condition  |                                                    |
| Drive Shaft Size           | Drive 2                                            |
| Special Accessories        | NONE                                               |
| Gear Working Condition     | Normal                                             |
| Gear Working Condition PTO | Repair                                             |
| Battery                    | No Have                                            |
| Battery Condition          | No Good                                            |
| Remark                     |                                                    |
| Details                    | More — บางรายการไม่สามารถเช็คได้ เพราะระบบไม่ทำงาน |

