



บริษัท สหเศรษฐ์ อ็อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : WHEEL LOADER Maker KOMATSU Model 530 Serial 01A-10446

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

*This report is only for your reference. We are not responsible for the actual condition of checked item

*** THAILAND DUTY PAID /ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
LOADER	WHEEL LOADER	KOMATSU	530
Serial	Engine	Chassis	Year
01A-10446	6D105-10740		
Check Point			
Operator		Cabin	
Monitor Panel		Repair	
Hour Meter Activity		Repair	
Air Condition		Non	
Remark			
Details		More — ภายนอกต้องซ่อมบำรุง	
Engine Condition			
Number of Cylinder (Cylinder)		6 Cylinder	
Engine Noise		Repair	
Black - White Smoke		Repair	
Type Transmission		Auto	
Gear Working Condition		Repair	
Water Leak from Water Pump		Repair	
Water Leak from Radiator		Repair	
Hydraulic System			
Oil leak from Valve-Hose			
Hyd.Pump Condition		Repair	
Hydraulic Oil		Repair	
Hydraulic Cylinder Working Condition			
Arm Cylinder Working Condition		Repair	
Bucket Cylinder Working Condition		Repair	
Oil Leak from Cylinder		Fair	
General Working Condition			
Bucket Condition		Fair — มีเข็มนาฬิกา	
Battery Condition		Non	