



บริษัท สหเศรษฐ์ อ็อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Maker KUBOTA Model L2600 Serial L2600-18471

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

*This report is only for your reference. We are not responsible for the actual condition of checked item

*** THAILAND DUTY PAID /ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	L2600
Serial	Engine	Chassis	Year
L2600-18471	V1500-10140		

Check point	
Operator	Roof
Monitor Panel	Normal — แสดงผลครบ
Hour Meter Activity	Normal — 5858
Air Condition	NONE
Engine Operation	
Number of Pistons	4 Pistons
Fuel Type	Diesel
Engine Noise	Fair
Black-White Smoke	Fair
Type Transmition	Manual
Water Leak form Water Pump	Normal
Water Leak form Radiater	Normal
Hydraulic System	
Oil Leak form Velve,Hose	Normal
HYD. Pump Condition	Repair
Hydraulic Oil	Repair
General Working Condition	
Drive Shaft Size	Drive 2
Special Accessories	NONE
Gear Working Condition	Normal
Gear Working Condition PTO	Repair
Battery	No Have
Battery Condition	No Good
Remark	
Details	More — บางรายการไม่สามารถเช็คได้ เพราะระบบไม่ทำงาน