บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Maker KUBOTA Model KB225-PC Serial BJ-10407

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	KB225-PC
Serial	**Engine**	**Chassis**	**Year**
BJ-10407	D1305-8E8181		

Check point	
Operator	NONE
Monitor Panel	Normal
Hour Meter Activity	Normal – 05038
Air Condition	NONE
Engine Operation	
Number of Pistons	3 Pistons
Fuel Type	Diesel
Engine Noise	Normal
Black-White Smoke	Normal
Type Transmition	Auto
Water Leak form Water Pump	Normal
Water Leak form Radiater	Fair
Hydraulic System	
Oil Leak form Velve,Hose	Fair
HYD. Pump Condiction	Fair
Hydraulic Oil	Fair
General Working Condition	
Drive Shaft Size	Drive 4
Special Accessories	NONE
Gear Working Condiction	Fair
Gear Working Condition PTO	Repair
Battery	Have
Battery Condition	No Good – ไฟเลี้ยง
Remark	
Details	More – ยางหน้า หลังแทรคยาง 33 ซม