



บริษัท สหเศรษฐ์ อ็อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : MINI EXCAVATOR Year 1999 Maker KOMATSU Model PC27R-8 Serial 11255

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
EXCAVATOR	MINI EXCAVATOR	KOMATSU	PC27R-8
Serial	Engine	Chassis	Year
11255	3D82AE-3F 10363		1999

Check Point	
Operator	Canopy — เบาะขาด สภาพตามอายุการใช้งาน
Monitor Panel Condition	Normal
Hour Meter Activity	Normal — 3260
Air Condition	Non
Remark	
Details	More — สภาพภายนอกพอใช้
Engine Condition	
Number of Cylinder (Cylinder)	3 Cylinder
Engine Noise	Normal
Black - White Smoke	Normal
Water Leak from Water Pump	Normal
Water Leak from Radiator	Normal
ระบบน้ำมันไฮดรอลิก/Hydraulic System	
Oil leak from Valve	Normal
Hyd.Pump Working Condition	Normal — ใช้งานได้ปกติ
Hydraulic Oil	Normal
Hydraulic Cylinder Working Condition	
Boom Cylinder Working Condition	Repair — รื้อซึม
Bucket Cylinder Working Condition	Repair — รื้อซึม
Arm Cylinder Working Condition	Repair — รื้อซึม
Blade Cylinder Working Condition	Normal — ขึ้นลงได้ตามปกติ
General Working Condition	
Swivel Bearing & Swivel Motor Condition	Normal
The overall condition of the undercarriage	Normal
Shoe Size (Centimeter)	Centimeter — แทรคยาง30ซม
Battery Condition	Have

