บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : FORKLIFT Year 1992 Maker TOYOTA Model 5FD25 Serial 5FD25-73017

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
FORKLIFT	FORKLIFT	TOYOTA	5FD25
Serial	**Engine**	**Chassis**	**Year**
5FD25-73017	1Z 0085940		1992

Check Point	
Operator	Canopy – เบาะ ขาด ตามอายุการใช้งาน
Monitor Panel	Normal – เช็คไม่ได้
Hour Meter Activity	Normal – ไม่แสดงผล
Air Condition	Non
Engine Operation	
Number of Cylinder	4 Cylinder – สตาร์ทไม่ติด ใช้เครื่องยนต์ไม่ได้
Fuel Type	Diesel
Engine Noise	
Black - White Smoke	
Type Transmission	Manual
Gear Working Condition	
Water Leak from Water Pump	
Water Leak from Radiator	
Remark	
Details	
Hydraulic System	
Oil leak from Valve,Hose	
Hyd.Pump Condition	
Hydraulic Oil	
Hydraulic Cylinder Working Condition	
Lift fork Cylinder Working Condition	
Tilt Mast Cylinder Working Condition	
General Working Condition	
SIze of Mast	2 Pieces
The Height of Mast	Centimeter – 300
Special features of Mast	Full Free
Special features of Fork	Hing fork
The Length of Fork	Centimeter – 90
Characteristics of Rubber	Pneumatic Tires – หน้า-หลัง ,หน้าคู่
Battery Condition	Have – ต้องพ่วง