บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : FORKLIFT Year 2005 Maker KOMATSU Model FD25C-16 Serial M228-710515

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
FORKLIFT	FORKLIFT	KOMATSU	FD25C-16
Serial	**Engine**	**Chassis**	**Year**
M228-710515	4D94LE 08165		2005

Check Point	
Operator	Canopy – เบาะ ขาด ตามอายุการใช้งาน
Monitor Panel	Normal – เช็คไม่ได้
Hour Meter Activity	Normal – ไม่แสดง
Air Condition	Non
Engine Operation	
Number of Cylinder	4 Cylinder
Fuel Type	Diesel
Engine Noise	Repair – เครื่องไม่หมุน สตาร์ทไม่ติด
Black - White Smoke	Normal – เครื่องไม่หมุน สตาร์ทไม่ติด
Type Transmission	Manual
Gear Working Condition	Repair – สถานะ จอดขาย
Water Leak from Water Pump	
Water Leak from Radiator	
Remark	
Details	
Hydraulic System	
Oil leak from Valve,Hose	
Hyd.Pump Condition	
Hydraulic Oil	
Hydraulic Cylinder Working Condition	
Lift fork Cylinder Working Condition	
Tilt Mast Cylinder Working Condition	
General Working Condition	
SIze of Mast	2 Pieces
The Height of Mast	Centimeter – 300
Special features of Mast	Normal
Special features of Fork	Slide Shift
The Length of Fork	Centimeter – 180
Characteristics of Rubber	Other – ลมคู่หน้า,คู่หลังตัด
Battery Condition	Non – ต้องพ่วง