บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Year 1973 Maker MITSUBISHI Model D1500V Serial M71B-10561

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 20% THAI IMPORT DUTY / มีค่าอากรนำเข้า 20%

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	MITSUBISHI	D1500V
Serial	**Engine**	**Chassis**	**Year**
M71B-10561	30308		1973

Check point	
Operator	NONE – เบาะขาด ตามสภาพ
Monitor Panel	NONE
Hour Meter Activity	NONE
Air Condition	NONE
Engine Operation	
Number of Pistons	2 Pistons – ไม่เยิ้ม แห้ง
Fuel Type	Diesel
Engine Noise	Normal
Black-White Smoke	Normal
Type Transmition	Manual
Water Leak form Water Pump	Normal
Water Leak form Radiater	Normal
Hydraulic System	
Oil Leak form Velve,Hose	Normal
HYD. Pump Condiction	Normal – ใช้งานได้
Hydraulic Oil	Normal
General Working Condition	
Drive Shaft Size	Drive 2
Special Accessories	Rotary
Gear Working Condiction	Normal
Gear Working Condition PTO	Normal – ใช้งานได้ปกติ
Battery	Have
Battery Condition	Good – สตาร์ทติด ใช้งานได้เลย
Remark	
Details	