บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : WHEEL LOADER Maker KOMATSU Model 530 Serial 01A-10446

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
LOADER	WHEEL LOADER	KOMATSU	530
Serial	**Engine**	**Chassis**	**Year**
01A-10446	6D105-10740		

Check Point	
Operator	Cabin
Monitor Panel	Repair
Hour Meter Activity	Repair
Air Condition	Non
Remark	
Details	More – ภายนอกต้องซ่อมบำรุง
Engine Condition	
Number of Cylinder (Cylinder)	6 Cylinder
Engine Noise	Repair
Black - White Smoke	Repair
Type Transmission	Auto
Gear Working Condition	Repair
Water Leak from Water Pump	Repair
Water Leak from Radiator	Repair
Hydraulic System	
Oil leak from Valve-Hose	
Hyd.Pump Condition	Repair
Hydraulic Oil	Repair
Hydraulic Cylinder Working Condition	
Arm Cylinder Working Condition	Repair
Bucket Cylinder Working Condition	Repair
Oil Leak from Cylinder	Fair
General Working Condition	
Bucket Condition	Fair – มีเชื่อม ปะรอยผุ
Battery Condition	Non