



บริษัท สหเครน อีออกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : MANLIFT Year 2007 Maker MAEDA Model HF090-3 Serial NU0930765

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
MANLIFT	MANLIFT	MAEDA	HF090-3
Serial	Engine	Chassis	Year
NU0930765	S3L 149019 F7		2007

Check point	
Operator	Boom Lift&Waist Swing
Propulsion	Engine — 3สูบ
Basket Size	
Battery size	NONE
Engine Size	3 Pistons
Hour Meter Activity	Hour — 2113
General Working Condition	
Engine Operation	Normal
Working of Hydraulic Pump	Normal
Operation of The Working Motor	Normal
Basket height	Cantimeter — 900
Number of batteries	1 unit
Hydraulic System	
Oil leak from Valve,Hose	Normal
HYD. Pump Condition	Normal
Hydraulic Oil	Normal
Remark	
Details	More — สภาพภายนอก ต้องซ่อมบำรุง

