



บริษัท สหเศรษฐ์ อ็อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : MINI EXCAVATOR Year 1991 Maker KOMATSU Model PC03-1 Serial 1917

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
EXCAVATOR	MINI EXCAVATOR	KOMATSU	PC03-1
Serial	Engine	Chassis	Year
1917	1D84-1A 00926		1991

Check Point	
Operator	Non — ซ่อม เบาะขาด สภาพไม่พร้อมใช้งาน หลังคาบุฟุ้ง
Monitor Panel Condition	Normal — ไม่มี
Hour Meter Activity	Normal — ไม่มี
Air Condition	Non
Remark	
Details	More — สภาพภายนอกพอใช้ สถานะจอด ใช้งานไม่ได้
Engine Condition	
Number of Cylinder (Cylinder)	Cylinder — 1สูบ
Engine Noise	
Black - White Smoke	
Water Leak from Water Pump	
Water Leak from Radiator	
ระบบน้ำมันไฮดรอลิก/Hydraulic System	
Oil leak from Valve	
Hyd.Pump Working Condition	Repair
Hydraulic Oil	Repair
Hydraulic Cylinder Working Condition	
Boom Cylinder Working Condition	Repair
Bucket Cylinder Working Condition	
Arm Cylinder Working Condition	
Blade Cylinder Working Condition	
General Working Condition	
Swivel Bearing & Swivel Motor Condition	
The overall condition of the undercarriage	Normal
Shoe Size (Centimeter)	Centimeter — แทรคยาง 20 ซม.เปลี่ยนสภาพ มีเส้น ไม่มีเส้น
Battery Condition	Non

