บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : TIRE ROLLER Year 2004 Maker DYNAPAC Model CP210 Serial *8UBP010139*

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
ROLLER	TIRE ROLLER	DYNAPAC	CP210
Serial	**Engine**	**Chassis**	**Year**
8UBP010139	4BG1 178114		2004

Check Point	
Operator	Canopy
Monitor Panel	Normal – แสดงผลครบ
Hour Meter Activity	Normal – 13702
Air Condition	Non
Remark	
Details	More – สภาพภายนอกเสื่อมสภาพ
Engine Condition	
Number of Cylinder	4 Cylinder
Engine Noise	Normal
Black - White Smoke	Normal
Type Transmission	Auto
Gear Working Condition	Normal – เดินหน้าถอยหลังได้ปกติ
Water Leak from Water Pump	Normal
Water Leak from Radiator	Fair
Hydraulic System	
Oil leak from Valve-Hose	Fair
Hyd.Pump Condition	Normal
Hydraulic Oil	Normal
General Working Condition	
Number of Wheel	7 Wheels – หน้า3หลัง4
Driving Chain Condition	Fair
Suction Pump, Drainage Pump	Fair
Suction Pump, Drainage Pump	Fair
Water Hose Condition	Repair
Front-Rear Sprinkler	Repair
Battery Condition	Have