บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : TIRE ROLLER Year 1990 Maker SAKAI Model TS31 Serial TTS2-10571

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
ROLLER	TIRE ROLLER	SAKAI	TS31
Serial	**Engine**	**Chassis**	**Year**
TTS2-10571	DH1102-3166		1990

Check Point	
Operator	Canopy
Monitor Panel	Normal
Hour Meter Activity	Normal – 6956
Air Condition	Non
Remark	
Details	More – สภาพภายนอกเสื่อมสภาพ
Engine Condition	
Number of Cylinder	3 Cylinder
Engine Noise	Normal
Black - White Smoke	Normal
Type Transmission	Manual
Gear Working Condition	Normal – เดินหน้าถอยหลังได้ปกติ
Water Leak from Water Pump	Normal
Water Leak from Radiator	Normal
Hydraulic System	
Oil leak from Valve-Hose	Normal
Hyd.Pump Condition	Normal
Hydraulic Oil	Normal
General Working Condition	
Number of Wheel	7 Wheels – หน้า4หลัง3
Driving Chain Condition	Fair
Suction Pump, Drainage Pump	Fair
Suction Pump, Drainage Pump	
Water Hose Condition	Fair
Front-Rear Sprinkler	Fair – ตามสภาพและอายุการใช้งาน
Battery Condition	Have