



บริษัท สหเครน อ็อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : CRAWLER CRANE Year 2015 Maker MAEDA Model LC785M-8 Serial 32313

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
CRANE	CRAWLER CRANE	MAEDA	LC785M-8
Serial	Engine	Chassis	Year
32313	4D95L-558395		2015

Check Point	
Operator	Cabin — กระจกประตูแตก
Hour Meter Activity	Normal — 2552
Monitor Panel Condition	Normal
Air Condition	Normal
Engine Condition	
Number of Cylinder (Cylinder)	4 Cylinder — 4D95L
Engine Noise	Normal
Black - White Smoke	Normal
Water Leak from Water Pump	Normal
Water Leak from Radiator	Normal
Hydraulic System	
Oil leak from Valve	Normal
Hyd.Pump Working Condition	Normal
Hydraulic Oil	Normal
Hydraulic Cylinder Working Condition	
Boom Cylinder Working Condition	Normal
Arm Cylinder Working Condition	Normal
General Working Condition	
The overall condition of the undercarriage	Normal
Shoe Size (Centimeter)	Normal — 50 ซม.□
Battery Condition	Good
Remark	
Details	More

